



TEST REPORT

Client: Camira Fabrics Ltd
The Watermill
Wheatley Park
Mirfield
WF14 8HE

Entry No: 103842

Date received: 11/12/2018

Client's Description: Yordale Run:393668 Colour: D900GB

Test Required: Abrasion.

Conditioning: In accordance with BS EN ISO 139: 2005 for a minimum of 24 hours at 65+/-4%, Relative Humidity, 20+/-2°C

Date Tests Completed: 25/01/2019

Abrasion Resistance: BS EN ISO 12947-2: 2016^F

The tests were carried out using a pressure of 12 +/- 0.3 kPa
The criterion for judging end point was two threads broken.

| | |
|-----------------------|--------------------|
| Specimen 1 | 90,000 rubs |
| Specimen 2 | 90,000 rubs |
| Specimen 3 | 80,000 rubs |
| Specimen 4 | 90,000 rubs |
| Overall Result | 80,000 rubs |

Change in colour after 6,000 rubs: 4-5

Observation Technique: 10 fold magnification
Type of Fabric: Flat Woven.

-----End of Document-----

This is hereby certified to be a correct return of the tests made of the items referred to herein



Claire Saville
Technologist
25th January 2019

- ❖ Unless instructed otherwise by the client sample remnants will be disposed of after 28 days.
 - ❖ Tests marked ^N in this certificate are not included in the UKAS Accreditation Schedule for this Laboratory.
 - ❖ Tests marked ^F in this certificate are performed under the Laboratory's Flexible Scope of Accreditation.
 - ❖ Tests marked ^S in this certificate have been subcontracted to another ISO17025 Accredited Laboratory.
 - ❖ Opinions and interpretations expressed herein are outside the scope of UKAS accreditation.
 - ❖ Uncertainty budgets for test methods contained within this report are available on request.
- This Certificate relates only to the sample received and, unless that sample has been drawn by the staff of this laboratory, or its agent, and endorsed accordingly, any application of the result to a bulk quantity or other material is entirely the responsibility of the client.



1104